



November 28<sup>th</sup>, 2023

Building Officials  
Pembroke Pines Building Department  
601 City Center Way  
Pembroke Pines, FL 33025

Re: Heron Pond Condominium  
Structural Conditions – Building #1  
Updated Findings

Dear Building Officials:

Since the end of July of this year a representative of ACG Engineering Services, Inc. (ACG), acting on my behalf, has surveyed all nineteen buildings at the Heron Pond Condominium complex. We have attached a copy of drawing S-3.0, a plan reflecting our findings from our survey of the structural conditions for Building #1. This sheet will be submitted with the set of permit drawings for the repair project. This report is being submitted subsequent to full perimeter destructive observations conducted at Buildings #2 and #3 and spot-check destructive observations made at Buildings #5 and #10. We have learned the following:

- Those findings at Buildings #2, #3, #5, and #10 have confirmed that the visual indications (from the non-destructive observation phase) are accurate – areas observed to reflect damage in fact have revealed damage and those areas not noted to reflect damage have been generally found to be damage-free.
- The termite damage to the exterior walls appears to have originated with the paneling used as exterior sheathing. Termite “tunneling” appeared to run in between the inside face of the paneling and the exterior faces of the wall 2x4 members.
- The balconies, the portions of the building structures permanently and fully exposed to the weather and elements, have sustained the worst of the wood damage.
- The bay windows, portions of the building structure whose undersides are permanently exposed to the weather and elements, have also sustained significant levels of damage.
- Even the balcony damage appears to lessen as the affected structural members get further away from the outside balcony edges.
- A number of the building corners have sustained significant structural damage.
- To date, none of the second-floor trusses exposed by stucco and sheathing removal show section loss or compromise.
- The sections of the second-floor wall that have been exposed, even when directly adjacent to first floor wall damage, have been observed to be intact, with no appreciable damage witnessed.
- In summary, to date, what has been exposed strongly suggests that the floor and roof trusses, except where sections of floors have been noted as being “soft” or “bouncy”, have not been compromised by termite or water damage.
- What has been exposed to date also demonstrates that the damage to the exterior wall 2x4 structure is intermittent; that is to say that much of the wall 2x4 structure is intact and need not be replaced.



Based on our original report of our survey findings for this building, combined with what we have since observed, as part of destructive observation of portions of Buildings #2, #3, #5, and #10, we offer the following summary:

A summary of our **findings** is as follows:

- Three of the balconies are shored (#206, #207, and #208) with two additional ones (#201 and #205) appearing to need shoring.
- Signs of water damage were observed in Units #103, #104, #107, #201, #203, and #206.
- There are at least 32 different locations around the building where damage has been visually detected, involving all 16 units.
- Additionally, signs of previous repairs have been noted at 35 other locations around the building.
- There are signs of damage or old repairs visible on all eight (8) balcony stacks.
- There are signs of damage to sections of exterior walls that appear to carry significant second floor and roof loads.
- There are five (5) locations where damage has been observed in sections of the structure that clearly appear to have been previously repaired; in these locations fresh signs of damage are telegraphing through the finishes.
- Based on our limited observations we do not know, with any level of certainty, how many additional conditions may exist that currently remain hidden under floors, above ceilings, and behind walls.

Our findings lead to the following **concerns**:

- The balconies for Units #201 and #205 are visibly damaged, but all balconies should be shored.
- The signs of water damage observed in Units #101, #103, #104, #201, #203, and #206 may reflect sections of weakened structure.
- Damage sustained by the exterior structural components, sections of the walls, all balconies, and bay windows, in the form of termite and water related wood deterioration, is significant.
- Of additional concern is that approximately 14% of recently repaired sections are already showing new signs of deterioration. All previous repair areas should be re-addressed.
- All of the balcony stack structures, including joists, beams, and columns, have sustained significant structural damage.
- Some of the apparently compromised sections of exterior wall appear to carry considerable 2<sup>nd</sup> floor and/or roof loads, but do not appear to pose a safety concern at the present time. Prior to the removal of any structure during the repair process, the second floor and roof structures should be adequately shored.

Based on our concerns, we **recommend** the following:

- The flooring and/or the ceiling should be removed, as required, to address the noted damages in the interiors of Units #101, #103, #104, #201, #203, and #206.
- All access to all balconies (both levels) must be prohibited until repairs have been made.
- All balcony ceilings should be removed to allow for visual observations of the second floor and roof structures.



- All second-floor balcony and bay window structures should be shored and then rebuilt as required.
- All roof trusses over the second-floor balconies shall be repaired as required.
- Damages that do extend into the interior of the building must be identified and repaired upon discovery.
- Wall bulges, cracks, and delaminations must be removed and those wall sections repaired in accordance with the loads that they carry.
- Based on findings, it is not necessary to vacate the interiors of any units until such time as the repair project has commenced.
- During the repair project for this building, the building should be vacated to allow for an expeditious repair process and to prohibit the presence of non-construction personnel on an active construction site.


The destructive observations made at Buildings #2, #3, #5, and #10 and their close correlation with the non-destructive visual inspections of those buildings confirm that the observations made by visual inspection of this building provide an accurate assessment of the structural damage sustained by this building's structure. In general, it is my professional opinion, to the best of my knowledge, that less than 25% of the structure has sustained damage. All sections that have sustained damage shall be repaired and/or replaced.

We have provided, attached to this report, photographs from our destructive observations of Building #2.

Please do not hesitate to let us know if you have any additional questions, comments, or concerns. Thank you.

Respectfully submitted,

Henry S. Kreh, P.E.  
Vice President  
ACG Engineering Services, Inc.  
FL PE No. 39539/FL SI No. 736



**PHOTOGRAPHS**



Photo #1 – Removed Severely Damaged Exterior Balcony Beam/  
Revealing Adjacent Joist with Only Limited Damage



Photo #2 – Progression of Joist Damage/Each Joist, Moving in from  
The Edge, Shows Less and Less Damage



Photo #3 – Damage to Vertical Wall 2x4, Showing Termite “Tunneling”  
Damage with the Deterioration on the 2x4 Face Adjacent to  
The Exterior Panel (Not Shown)



Photo #4 – The Exterior Balcony Beam Has Been Completely Damaged And Removed/This Balcony Structure Damage is Severe



Photo #5 – The Floor Joist Most Directly Adjacent to the Removed Wall Panel Shows No Signs of Damage




Photo #6 – Water Damage Is Evident, Having Affected the Sheathing at Both Corners




Photo #7 – Sheathing Stripped from Both Levels of Wall/Showing That the Extensive Damage to the First Level Wall Does Not Translate to the Second Floor Wall Structure

SECOND FLOOR  
BLDG. #1



GROUND FLOOR  
BLDG. #1



NOTES:  
ALL LOCATIONS WHERE DAMAGES  
ARE FOUND WILL BE INVESTIGATED  
TO ASURE NO UNDERLYING  
STRUCTURAL DAMAGES.

DATE	DESCRIPTION	REV



HENRY S. KREH  
FL P.E. #39539